


REVERSIBLE GAUGE MOUNTING PLATE

Models TSA750, TSA750H, TSC1000, TSC1000H, TSF, and TSFH include a reversible force gauge mounting plate to accommodate all Mark-10 force gauges except Series E.

Reverse the plate by removing two screws, as shown, then flip it around and reinstall.



Manual Test Stands

QUICK START GUIDE

Models: ES05 / ES10 / ES20 / ES30 / TSB100 / TSA750 / TSA750H / TSC1000 / TSC1000H / TSF / TSFH / TST / TSTH

Thank you!

Thank you for purchasing a Mark-10 manual test stand. With proper usage, we are confident that you will get many years of great service with this product. Mark-10 test stands are ruggedly built for laboratory and industrial environments. Please read through this quick start guide and the complete user's guide before using the test stand.



MODEL ES05

Compression-only test stand. Shipped fully assembled, and includes the following:

Qty.	Item
4	Thumb screws for force gauge mounting
1	Allen wrench set



MODELS ES10 & ES20

Tension/compression test stands. Shipped mostly assembled, and include the following:

Qty.	Item
1	Lever (ES10) or handwheel (ES20), assembly required
4	Thumb screws for force gauge mounting
1	Optional digital or dial indicator
1	Allen wrench set



MODEL ES30

Tension/compression test stand. Shipped mostly assembled, and includes the following:

Qty.	Item
1	Handwheel (assembly required)
4	Thumb screws for force gauge mounting
1	Set of accessories (refer to the user's guide for a complete list)
1	Optional digital travel display
1	Allen wrench set



MODELS TSA750 & TSA750H

Tension/compression test stands. Shipped mostly assembled, and include the following:

Qty.	Item
1	Lever (assembly required)
8	Thumb screws for force gauge mounting, 4 for lower capacity gauges, 4 for higher capacity gauges
1	Set of mounting legs with column cap (TSA750H), assembly required
1	Set of accessories (refer to the user's guide for a complete list)
1	Optional digital travel display
1	Allen wrench set



MODELS TSC1000 & TSC1000H

Tension/compression test stands. Shipped mostly assembled, and include the following:

Qty.	Item
8	Thumb screws for force gauge mounting, 4 for lower capacity gauges, 4 for higher capacity gauges
1	Set of mounting legs with column cap (TSC1000H), assembly required
1	Set of accessories (refer to the user's guide for a complete list)
1	Optional digital travel display
1	Allen wrench set



MODELS TSF & TSF1000H

Tension/compression test stands. Shipped mostly assembled, and include the following:

Qty.	Item
1	Lever (assembly required)
8	Thumb screws for force gauge mounting - 4 for lower capacity gauges, 4 for higher capacity gauges
1	Base (TSF) or set of mounting legs with column cap (TSFH), assembly required
1	Set of accessories (refer to the user's guide for a complete list)
1	Optional digital travel display
1	Allen wrench set



MODELS TST & TSTH

Clockwise/counter-clockwise torque test stands. Shipped mostly assembled, and include the following:

Qty.	Item
1	Indicator mounting kit (assembly required)
4	Thumb screws for indicator mounting
1	Base (TST) or set of mounting legs with column cap (TSTH), assembly required
1	Optional digital angle indicator
1	Allen wrench set



MODEL TSB100

Tension/compression test stands. Shipped fully assembled, and includes the following:

Qty.	Item
1	Lever (assembly required)
4	Thumb screws for force gauge mounting
1	G1030 thread adapter, 5/16-18M to #10-32F
1	Optional digital travel display
1	Optional travel stops kit
1	Allen wrench set